	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

GENERAL INFORMATION

Client name	ADEO SERVICES
Service name	Final Random Inspection
Supplier name	SHANDONG BOSS ABRASIVES MANUFACTURING CO.,LTD.
Factory name	SHANDONG BOSS ABRASIVES MANUFACTURING CO.,LTD.
Factory address	NO.1 Zhuangke Industrial Area, Suncun, Jinan, Shandong, China
PO number	S2009351968
Product ref	Multiple, refer to ORDER DETAILS
Product desc.	Multiple, refer to ORDER DETAILS
Destination country	FRANCE
Insp. Date	23/08/2021 to 26/08/2021
Inspection office	API SUZHOU
Inspector Name	Edison ZHAO
Production status	100%
Packing status	100%




INSPECTION SUMMARY

Criteria		Results	Remarks
A	Quantity	PASS	
B	Workmanship	PASS	
C	Product specifications	PASS	
D	Packing	PASS	
E	Onsite tests	PASS	
F	Other information	PASS	
OVERALL RESULT		PASS	

WORKMANSHIP SUMMARY

Inspection Standard	ANSI/ASQ Z1.4	AQL	Critical - 0	Major - 1.5	Minor - 4
Inspection Level	Level II				
Sampling plan	Normal, Single	Sampling size	500	500	315
Sampling size	500 (Combined)	Max	0	14	21
Lot size	37000	Found	0	0	0
		Result	PASS	PASS	PASS

ORDER DETAILS

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	


#	Product ref	Item description	EAN #	PO	Insp. Qty	Sample size
1	855956	DEXTER-WATER PAPER ,230X280, G400,1PC -PRINTING 1C. - METAL/ PLASTIC	3276006178921	S2009351968	5000	67
2	855957	DEXTER-WATER PAPER ,230X280, G240,1PC -PRINTING 1C. - METAL/ PLASTIC	3276006178907	S2009351968	4000	55
3	855997	DEXTER-WATER PAPER ,230X280, G500, 1P C-PRINTING 1C. - METAL/PLASTIC	3276006179218	S2009351968	4000	54
4	855998	DEXTER-WATER PAPER ,230X280, G280,1PC -PRINTING 1C. - METAL/PLASTIC	3276006179201	S2009351968	4000	54
5	856002	DEXTER-WATER PAPER ,230X280, G600,1PC -PRINTING 1C. - METAL/ PLASTIC	3276006178945	S2009351968	13000	175
6	856079	DEXTER-WATER PAPER ,230X280, G320,1PC -PRINTING 1C. - METAL/ PLASTIC	3276006178914	S2009351968	4000	54
7	856088	DEXTER-WATER PAPER ,230X280, G1000, 1 PC-PRINTING 1C. - METAL/PLASTIC	3276006179232	S2009351968	3000	41
Total					37000	500 (Combined)

PROBLEMATIC REMARKS

#	Product ref	Remarks	Category	Result
1	All	Nil		

COMMENTS FOR INFORMATION

#	Product ref	Comments
1	All	Logistic data is over +/-5% tolerance, please refer to details in Logistic Data list

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

A - QUANTITY

Overall Result	PASS
-----------------------	-------------


AVAILABLE QUANTITIES

#	Product ref	PO No.	Booking QTY		Available QTY			Total	
					Finished & Packed	Finished & unpacked	Not Finished	% Finished	% Packed
			Units	Cartons	Units	Units	Units		
1	855956	S2009351968	5000	5	5000	0	0	100.00	100.00
2	855957	S2009351968	4000	5	4000	0	0	100.00	100.00
3	855997	S2009351968	4000	4	4000	0	0	100.00	100.00
4	855998	S2009351968	4000	5	4000	0	0	100.00	100.00
5	856002	S2009351968	13000	13	13000	0	0	100.00	100.00
6	856079	S2009351968	4000	4	4000	0	0	100.00	100.00
7	856088	S2009351968	3000	3	3000	0	0	100.00	100.00
Total			37000	39	37000	0	0	100%	100%

SELECTED CARTONS QUANTITY

#	Product ref	PO No.	Batch No.	Select CTN QTY	CTN No.
1	855956	S2009351968	07/21	3	1, 3, 5
2	855957	S2009351968	07/21	3	1, 2, 3
3	855997	S2009351968	07/21	3	1, 3, 4
4	855998	S2009351968	07/21	3	1, 3, 5
5	856002	S2009351968	07/21	3	3, 9, 11
6	856079	S2009351968	07/21	3	2, 3, 4
7	856088	S2009351968	07/21	3	1, 2, 3
Total				21	

PHOTOS

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	


B - WORKMANSHIP

Overall Result	PASS
-----------------------	-------------

DEFECTS RESULT

#	Product ref	Defect description	Sample size	Defect classification		
				Critical 0	Major 1.5	Minor 4
Sample size				500	500	315
Maximum Allowed				0	14	21
Number of Defects Found				0	0	0
Workmanship Result				PASS	PASS	PASS

PHOTOS

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

C - PRODUCT SPECIFICATIONS


Overall Result	PASS
-----------------------	-------------

PRODUCT DIMENSION W/O PACKAGING


* Tolerance used:		API Generic	Sample size:		1	Unit:	mm	Tolerance Type:		%	Tolerance apply on:		Individual	
#	Product ref	Spec from client Values			Dimension pack info Values			Tol. *	# Pcs	Measured values			Discrepancy to Spec	Discrepancy to Pack info
		L	W	H	L	W	H			L	W	H		
1	855956	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%
2	855957	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%
3	855997	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%
4	855998	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%
5	856002	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%
6	856079	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%
7	856088	230	280		230	280		3	1	230	280		L +0% W +0% H N/A%	L +0% W +0% H N/A%

PRODUCT WEIGHT W/O PACKAGING

* Tolerance used:	API Generic	Sample size:	1	Unit:	g	Tolerance Type:	%	
#	Product ref	Spec from client Values	Weight on pack Values	Tol. *	# Pcs	Measured values	Discrepancy to Spec	Discrepancy to Pack info
1	855956			10	1	12	N/A	N/A
2	855957			10	1	15	N/A	N/A
3	855997			10	1	12	N/A	N/A
4	855998			10	1	15	N/A	N/A
5	856002			10	1	11	N/A	N/A
6	856079			10	1	14	N/A	N/A
7	856088			10	1	10	N/A	N/A

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

PHOTOS

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

D - PACKING

FINDINGS

#	Product ref	Subcategory	Remark	Result
1	All	Weight	Logistic data is over +/-5% tolerance, please refer to details in Logistic Data list	COMMENT
Overall Result				PASS


BARCODES (SAMPLE SIZE: DELIVERY PACKING 5 PCS, SALES PACKING S-3)

#	Product ref	Packing type	Barcode	Visual check			Scancheck		
				Sample	Fail	Pass	Sample	Fail	Pass

PACKING MATERIAL - OUTER CARTON

#	Product ref	Export Carton	Corrugated paper plies	Fastening	Tape Sealing	Strapping	Others
1	All	New	Double	Glue	Transparent	No	


PHOTOS

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

E - ONSITE TESTS

#	Description	Level	Sample size	Fail	Pass	Comments	Result
1	Function Check	S3	32	0	32		PASS
2	Marking check	S3	32	0	32		PASS
3	Part List Check	II	500	0	500		PASS
4	odor check	Custom	32	0	32		PASS
5	country speciality check	Custom	7	0	7		PASS
Overall Result							PASS

PHOTOS

	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

F - OTHER INFORMATION

Overall Result	PASS
-----------------------	-------------

DOCUMENTS AVAILABLE DURING INSPECTION

#	Inspection is performed with
1	TCF, booking ,PO ,OC and approval sample

TYPE OF SAMPLE AVAILABLE DURING INSPECTION

#	Product ref	Type of Sample	Description	Quantity	Comments
1	All	Golden sample	product	1	

PHOTOS

PICTURES


General

#1 export carton



#2 stamp



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#3 shipping mark



#4 open ctn



#5 inner box



#6 inner box




#7 inner box



#8 inner box



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#9 shipping mark




#10 open box



#11 product



#12 product




#13 product



#14 product



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#15 dimension check



#16 dimension check



#17 weight check



#18 855957




#19 855957



#20 855957



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#21 855957



#22 855957



#23 855957



#24 855957




#25 855957



#26 855957



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#27 855957



#28 855957



#29 855957



#30 855957




#31 855997



#32 855997



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#33 855997



#34 855997




#35 855997



#36 855997




#37 855997



#38 855997



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#39 855997



#40 855997



#41 855997



#42 855997




#43 855997



#44 855998



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#45 855998



#46 855998



#47 855998




#48 855998




#49 855998



#50 855998



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#51 855998



#52 855998



#53 855998



#54 855998




#55 855998



#56 855998



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#57 856002



#58 856002



#59 856002



#60 856002




#61 856002



#62 856002



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#63 856002



#64 856002



#65 856002



#66 856002




#67 856002



#68 856002



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#69 856002



#70 856079



#71 856079



#72 856079




#73 856079



#74 856079



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#75 856079



#76 856079



#77 856079



#78 856079




#79 856079




#80 856079



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#81 856079



#82 856079



#83 856088



#84 856088




#85 856088



#86 856088



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	


#87 856088



#88 856088



#89 856088



#90 856088




#91 856088



#92 856088



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#93 856088



#94 856088



#95 856088



#96 sample




#97 sample




#98 sample



	INSPECTION REPORT		PASS
	Inspection No	36881	
	Product ref	Multiple, refer to ORDER DETAILS	
	Report No	36881-4	

#99 barcode scan



Item	Quantity	Status
36881-1-10001	1	OK
36881-1-10002	1	OK
36881-1-10003	1	OK
36881-1-10004	1	OK
36881-1-10005	1	OK
36881-1-10006	1	OK
36881-1-10007	1	OK
36881-1-10008	1	OK
36881-1-10009	1	OK
36881-1-10010	1	OK
36881-1-10011	1	OK
36881-1-10012	1	OK
36881-1-10013	1	OK
36881-1-10014	1	OK
36881-1-10015	1	OK
36881-1-10016	1	OK
36881-1-10017	1	OK
36881-1-10018	1	OK
36881-1-10019	1	OK
36881-1-10020	1	OK
36881-1-10021	1	OK
36881-1-10022	1	OK
36881-1-10023	1	OK
36881-1-10024	1	OK
36881-1-10025	1	OK
36881-1-10026	1	OK
36881-1-10027	1	OK
36881-1-10028	1	OK
36881-1-10029	1	OK
36881-1-10030	1	OK
36881-1-10031	1	OK
36881-1-10032	1	OK
36881-1-10033	1	OK
36881-1-10034	1	OK
36881-1-10035	1	OK
36881-1-10036	1	OK
36881-1-10037	1	OK
36881-1-10038	1	OK
36881-1-10039	1	OK
36881-1-10040	1	OK
36881-1-10041	1	OK
36881-1-10042	1	OK
36881-1-10043	1	OK
36881-1-10044	1	OK
36881-1-10045	1	OK
36881-1-10046	1	OK
36881-1-10047	1	OK
36881-1-10048	1	OK
36881-1-10049	1	OK
36881-1-10050	1	OK
36881-1-10051	1	OK
36881-1-10052	1	OK
36881-1-10053	1	OK
36881-1-10054	1	OK
36881-1-10055	1	OK
36881-1-10056	1	OK
36881-1-10057	1	OK
36881-1-10058	1	OK
36881-1-10059	1	OK
36881-1-10060	1	OK
36881-1-10061	1	OK
36881-1-10062	1	OK
36881-1-10063	1	OK
36881-1-10064	1	OK
36881-1-10065	1	OK
36881-1-10066	1	OK
36881-1-10067	1	OK
36881-1-10068	1	OK
36881-1-10069	1	OK
36881-1-10070	1	OK
36881-1-10071	1	OK
36881-1-10072	1	OK
36881-1-10073	1	OK
36881-1-10074	1	OK
36881-1-10075	1	OK
36881-1-10076	1	OK
36881-1-10077	1	OK
36881-1-10078	1	OK
36881-1-10079	1	OK
36881-1-10080	1	OK
36881-1-10081	1	OK
36881-1-10082	1	OK
36881-1-10083	1	OK
36881-1-10084	1	OK
36881-1-10085	1	OK
36881-1-10086	1	OK
36881-1-10087	1	OK
36881-1-10088	1	OK
36881-1-10089	1	OK
36881-1-10090	1	OK
36881-1-10091	1	OK
36881-1-10092	1	OK
36881-1-10093	1	OK
36881-1-10094	1	OK
36881-1-10095	1	OK
36881-1-10096	1	OK
36881-1-10097	1	OK
36881-1-10098	1	OK
36881-1-10099	1	OK
36881-1-10100	1	OK

#100 warehouse



#101 open ctn




For and on Behalf of
Asia Pacific Inspection (API)

**** END OF REPORT ****