



API Inspection Report

											buckets)
833695	FD-D0975	15	5	67	1005	Y	Y	See LD	Y	PASS	
833696	FD-D0950	20	5	20	400	Y	Y	See LD	Y	PASS	
833697	FD-D09120	10	2	20	200	Y	Y	See LD	Y	PASS	
833698	FD-D0940	30	5	20	600	Y	Y	See LD	Y	PASS	
833699	FD-D0965	20	5	20	400	Y	Y	See LD	Y	PASS	
833700	FD-D0955	20	5	20	400	Y	Y	See LD	Y	PASS	
833701	FD-D0935	30	5	20	600	Y	Y	See LD	Y	PASS	
833702	FD-D0960	20	5	20	400	Y	Y	See LD	Y	PASS	
833703	FD-D0990	10	2	20	200	Y	Y	See LD	Y	PASS	
833704	FD-D09100	10	2	20	200	Y	Y	See LD	Y	PASS	
833705	FD-D0970	15	5	115	1725	Y	Y	See LD	Y	PASS	
833706	FD-D0968	15	5	119	1785	Y	Y	See LD	Y	PASS	
833707	FD-D0945	30	5	20	600	Y	Y	See LD	Y	PASS	
833708	FD-D09110	10	2	20	200	Y	Y	See LD	Y	PASS	
833709	FD-D0980	15	5	42	630	Y	Y	See LD	Y	PASS	
835257	FD-A0188	198	3	5	990	Y	Y	See LD	Y	PASS	
930039	FD-B020202	24	2	53	1272	Y	Y	50x14.5x13	Y	PASS	
930040	FD-B020102	24	2	17	408	Y	Y	50.5x14.5x13	Y	PASS	
930823	FD-A0024	48	6	42	2016	Y	Y	46x18x14.5	Y	PASS	
930825	FD-A0022	198	6	5	990	Y	Y	41.5x32x24	Y	PASS	
930828	FD-A0007	198	6	26	5148	Y	Y	40x25.5x24.5	Y	PASS	
930832	FD-A0215	48	3	5	240	Y	Y	110x12x11	Y	PASS	



API Inspection Report

930833	FD-A0214	18	3	26	468	Y	Y	90x10.5x10	Y	PASS	
930834	FD-A0213	18	3	5	90	Y	Y	90x12x10	Y	PASS	
930836	FD-A0211	24	3	24	576	Y	Y	90x12x10	Y	PASS	
930837	FD-A0207	48	3	8	384	Y	Y	90x11.5x10.5	Y	PASS	
930838	FD-A0206	18	3	48	864	Y	Y	70x15x10	Y	PASS	
930839	FD-A0204	24	3	39	936	Y	Y	70x12x12	Y	PASS	
930840	FD-A0203	24	3	10	240	Y	Y	70x12x11	Y	PASS	
930842	FD-A0201	24	3	36	864	Y	Y	70x10.5x10.5	Y	PASS	
930843	FD-A0200	24	3	73	1752	Y	Y	70x10x9	Y	PASS	
930844	FD-A0199	24	3	11	264	Y	Y	70x8x9	Y	PASS	
930846	FD-A0195	24	6	29	696	Y	Y	42x18.5x10	Y	PASS	
930847	FD-A0194	96	6	12	1152	Y	Y	41x26.5x18	Y	PASS	
930849	FD-A0190	48	6	23	1104	Y	Y	36x26.5x12	Y	PASS	
932070	FD-A0158	24	6	37	888	Y	Y	56x19x10	Y	PASS	
932071	FD-A0153	24	6	8	192	Y	Y	56x19x10.5	Y	PASS	
932074	FD-A0141	24	3	36	864	Y	Y	55x10.5x10.5	Y	PASS	
932079	FD-A0179	48	3	18	864	Y	Y	35.5x16.5x12	Y	PASS	
932080	FD-A0178	48	3	20	960	Y	Y	37x15.5x11.5	Y	PASS	
932082	FD-A0135	99	3	10	990	Y	Y	35.5x30.5x12	Y	PASS	
932087	FD-A0134	96	6	24	2304	Y	Y	34x32x18	Y	PASS	
932089	FD-A0122	198	6	17	3366	Y	Y	35x29x14.5	Y	PASS	
932092	FD-A0133	198	3	14	2772	Y	Y	40x24x10.5	Y	PASS	

C. Product Inspection (visual check)

#2, Validate thickness, shake test, hanging test, batch code position, printing, color, window, open & close of packaging...

API Inspection Report

#3, Validate assortment, finishing, color, workmanship,...

#4, for light weight product, uses at least 20pcs / batch / ref. So weight 20*2 = 40pcs and by calculation find the unit weight of the product. Acceptance allowance is +/- 2%

#5, photos are sent by separate files

Ref no	Unite barcode Inner barcode Outer barcode	Polybag/unit box/ label/hangtag Check #2			Product Check #3	Product dimension	Net weight /produ ct (g)	Carton weight (g) #4	Fit for use	Overall result Passed/Failed	Remarks on result	Product and defect photo numbers #5
		Mate rial	Shake/ hangin g test	Printin g/label ing								
833695	See L/D	Y	Y	Y	PASS	D75mm	824	13864 13757 13835 13363 13481 A.W: 13872	PASS	PASS		
833696	See L/D	Y	Y	Y	PASS	D50mm	582	12874 12765 12622 12578 13065 A.W: 12789	PASS	PASS		
833697	See L/D	Y	Y	Y	PASS	D120mm	1430	16174 16315 16059 16164 16295 A.W: 16198	PASS	PASS		

API Inspection Report

833698	See L/D	Y	Y	Y	PASS	D40mm	482	15968 15895 15558 15768 15939 A.W: 15825	PASS	PASS		
833699	See L/D	Y	Y	Y	PASS	D65mm	730	15486 15592 15811 15836 15579 A.W: 15688	PASS	PASS		
833700	See L/D	Y	Y	Y	PASS	D55mm	618	13668 13576 13877 13688 13636 A.W: 13687	PASS	PASS		
833701	See L/D	Y	Y	Y	PASS	D35mm	432	14378 14525 14435 14483 14239 A.W: 14395	PASS	PASS		
833702	See L/D	Y	Y	Y	PASS	D60mm	664	14582 14444 14787 14515 14485	PASS	PASS		



API Inspection Report

								A.W: 14576				
833703	See LD	Y	Y	Y	PASS	90mm	1020	11574 11576 11577 11583 11585 A.W: 11576	PASS	PASS		
833704	See LD	Y	Y	Y	PASS	100mm	1130	12714 12666 12658 12677 12682 A.W: 12659	PASS	PASS		
833705	See LD	Y	Y	Y	PASS	70mm	784	13092 13059 12988 12979 13175 A.W: 13074	PASS	PASS		
833706	See LD	Y	Y	Y	PASS	68mm	776	12840 12733 12611 12657 12579 A.W: 12653	PASS	PASS		
833707	See LD	Y	Y	Y	PASS	45mm	538	17696 17833 17871	PASS	PASS		



API Inspection Report

								17856 17858 A.W: 17855				
833708	See LD	Y	Y	Y	PASS	110mm	1290	14860 14712 14625 14711 14638 A.W: 14665	PASS	PASS		
833709	See LD	Y	Y	Y	PASS	80mm	902	15140 14522 14613 14528 14600 A.W: 14548	PASS	PASS		
835257	See LD	Y	Y	Y	PASS	110xdia10mm	48	11547 11578 11565 11556 11547 A.W: 11559	PASS	PASS		
930039	See LD	Y	Y	Y	PASS	400xdia25mm	730	18340 18334 18301 18376 18413 A.W: 18352.8	PASS	PASS		
930040	See LD	Y	Y	Y	PASS	400xdia18mm	706	17751	PASS	PASS		



API Inspection Report

								17824 17789 17868 17782 A.W: 17802.8				
930823	See LD	Y	Y	Y	PASS	350/280xdia12mm	164	9160 9079 8986 9033 9125 A.W: 9076.6	PASS	PASS		
930825	See LD	Y	Y	Y	PASS	210xdia10mm	88	20108 20089 20113 20092 20013 A.W: 20083	PASS	PASS		
930828	See LD	Y	Y	Y	PASS	110/42xdia6mm	40	10305 10111 10302 10278 10086 A.W: 10216.4	PASS	PASS		
930832	See LD	Y	Y	Y	PASS	1000/875xdia10m m	347	17749 17762 17774 17936 17845 A.W: 17813.2	PASS	PASS		

API Inspection Report

930833	See LD	Y	Y	Y	PASS	800/685xdia25mm	1384	25683 25861 25892 25913 25936 A.W: 25857	PASS	PASS		
930834	See LD	Y	Y	Y	PASS	800xdia22mm	1159	21443 21587 21912 21854 21634 A.W: 21686	PASS	PASS		
930836	See LD	Y	Y	Y	PASS	800xdia18mm	830	20747 20734 20912 20786 20819 A.W: 20799.6	PASS	PASS		
930837	See LD	Y	Y	Y	PASS	800xdia10mm	286	14376 14434 14485 14501 14468 A.W: 14452.8	PASS	PASS		
930838	See LD	Y	Y	Y	PASS	600/505xda25mm	1015	19062 18867 19093 19114 19055	PASS	PASS		



API Inspection Report

								A.W: 19038.2				
930839	See LD	Y	Y	Y	PASS	600/505xda22mm	842	20555 20721 20716 20686 20538 A.W: 20643.2	PASS	PASS		
930840	See LD	Y	Y	Y	PASS	600/505xdia20mm	733	18513 18678 18817 18934 18792 A.W: 18746.8	PASS	PASS		
930842	See LD	Y	Y	Y	PASS	600/505xdia16mm	466	11697 11343 11465 11401 11568 A.W: 11494.8	PASS	PASS		
930843	See LD	Y	Y	Y	PASS	600/505xdia14mm	342	8951 8865 8902 8777 8884 A.W: 8875.8	PASS	PASS		
930844	See LD	Y	Y	Y	PASS	600/505xdia12mm	251	6700 6546 6581	PASS	PASS		



API Inspection Report

								6634 6673 A.W: 6626.8				
930846	See LD	Y	Y	Y	PASS	310/220xdia22mm	420	10918 10889 11003 10856 10947 A.W: 10922.6	PASS	PASS		
930847	See LD	Y	Y	Y	PASS	310/235xdia10mm	111	12812 13009 12937 13035 13013 A.W: 12961.2	PASS	PASS		
930849	See LD	Y	Y	Y	PASS	260Xdia20mm	312	16140 16334 16289 16276 16178 A.W: 16243.4	PASS	PASS		
932070	See LD	Y	Y	Y	PASS	460xdia25mm	764	19468 19557 19525 19513 19519 A.W: 19516.4	PASS	PASS		
932071	See LD	Y	Y	Y	PASS	460xdia22mm	632	16451	PASS	PASS		

API Inspection Report


								16624 16670 16644 16678 A.W: 16613.4				
932074	See LD	Y	Y	Y	PASS	460xdia16mm	351	9011 9088 9112 8987 9135 A.W: 9066.6	PASS	PASS		
932079	See LD	Y	Y	Y	PASS	260xdia18mm	257	13070 12956 13018 12991 13100 A.W: 13027	PASS	PASS		
932080	See LD	Y	Y	Y	PASS	260dia16mm	196	10123 10278 10345 10325 10336 A.W: 10305	PASS	PASS		
932082	See LD	Y	Y	Y	PASS	260xdia14mm	151	16751 16711 16677 16768 16780 A.W: 16716.6	PASS	PASS		



API Inspection Report

932087	See LD	Y	Y	Y	PASS	210xdia14mm	124	14102 13986 13863 14062 13955 A.W: 13996.6	PASS	PASS		
932089	See LD	Y	Y	Y	PASS	210xdia10mm	79	18789 19026 19372 19459 19267 A.W: 19182.6	PASS	PASS		
932092	See LD	Y	Y	Y	PASS	210xdia14mm	96	20713 20673 20752 20833 20785 A.W: 20800.6	PASS	PASS		

Hardness Test:48~50

	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

PICTURES

Product Ref: 833695

#1 weight check-833709



#2 shipping label



#3 inner label



#4 packaging



#5 color label



#6 color label



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#7 product



#8 product



#9 product



#10 product



#11 weight check



#12 barcode scan



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#13 barcode scan



#14 barcode scan



#15 833705



#16 833705



#17 833705



#18 833705



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#19 833705



#20 833705



#21 833705



#22 833705



#23 833705



#24 833705



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#25 833705



#26 833706



#27 833706



#28 833706



#29 833706



#30 833706



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#31 833706



#32 833706



#33 833706



#34 833706



#35 833706



#36 833706



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#37 833702



#38 833702



#39 833702



#40 833702



#41 833702



#42 833702



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#43 833702



#44 833702



#45 833702



#46 833702




#47 833702



#48 833695



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#49 833695



#50 833695



#51 833695



#52 833695



#53 833695



#54 833695



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#55 833695



#56 833695



#57 833695



#58 833695




#59 833700



#60 833700



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#61 833700



#62 833700



#63 833700



#64 833700




#65 833700



#66 833700



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#67 833700



#68 833700



#69 833700



#70 833701



#71 833701



#72 833701



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#73 833701



#74 833701



#75 833701



#76 833701




#77 833701



#78 833701



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#79 833701



#80 833701



#81 833698



#82 833698



#83 833698



#84 833698



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#85 833698




#86 833698



#87 833698



#88 833698



#89 833698



#90 833698



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#91 833698



#92 833696



#93 833696



#94 833696



#95 833696



#96 833696



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#97 833696



#98 833696



#99 833696



#100 833696




#101 833696



#102 833696



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#103 833699



#104 833699



#105 833699



#106 833699



#107 833699



#108 833699



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#109 833699



#110 833699



#111 833699



#112 833699




#113 833699



#114 833707



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#115 833707



#116 833707



#117 833707



#118 833707



#119 833707



#120 833707



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#121 833707



#122 833707



#123 833707



#124 833707



#125 833708



#126 833708



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#127 833708



#128 833708



#129 833708



#130 833708



#131 833708



#132 833708



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#133 833708



#134 833708



#135 833708



#136 833704




#137 833704



#138 833704



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#139 833704



#140 833704



#141 833704



#142 833704



#143 833704



#144 833704



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#145 833704



#146 833704



#147 833704



#148 833703



#149 833703



#150 833703



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#151 833703



#152 833703



#153 833703



#154 833703



#155 833703



#156 833703



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#157 833703



#158 833703



#159 833703



#160 833703




#161 833697



#162 833697



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#169 833697



#170 833697



#171 833697



#172 930838



#173 930838



#174 930838



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#175 930838



#176 930838



#177 930838



#178 930838



#179 930838



#180 930838



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#181 930838



#182 930838



#183 930838



#184 930838



#185 930833



#186 930833



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#187 930833



#188 930833



#189 930833



#190 930833



#191 930833



#192 930833



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#193 930833



#194 930833



#195 930833



#196 930833



#197 930839




#198 930839



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#199 930839



#200 930839



#201 930839



#202 930839



#203 930839



#204 930839



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#205 930839



#206 930839



#207 930839



#208 930839



#209 930840



#210 930840



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#211 930840



#212 930840



#213 930840



#214 930840



#215 930840



#216 930840



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#217 930840



#218 930840



#219 930840



#220 930840



#221 930836



#222 930836



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#223 930836



#224 930836



#225 930836



#226 930836



#227 930836



#228 930836



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#229 930836



#230 930836



#231 930836



#232 930836



#233 930843



#234 930843



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1


#235 930843



#236 930843



#237 930843



#238 930843



#239 930843



#240 930843



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#241 930843



#242 930843



#243 930843



#244 930843




#245 930846



#246 930846



 <p>api CUSTOMIZED QUALITY ASSURANCE WORMS SAFETY</p>	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#247 930846



#248 930846



#249 930846



#250 930846



#251 930846



#252 930846



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#253 930846



#254 930846



#255 930846



#256 930846



#257 930842



#258 930842



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#259 930842



#260 930842



#261 930842



#262 930842



#263 930842



#264 930842



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#265 930842



#266 930842



#267 930837



#268 930837



#269 930837



#270 930837



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#271 930837



#272 930837



#273 930837



#274 930837




#275 930837



#276 930837



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#277 930837



#278 930837



#279 930834



#280 930834



#281 930834




#282 930834



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#283 930834



#284 930834



#285 930834



#286 930834



#287 930834



#288 930834



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#289 930834



#290 930834



#291 930832



#292 930832



#293 930832



#294 930832



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#295 930832



#296 930832



#297 930832



#298 930832



#299 930832



#300 930832



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#301 930832



#302 930832



#303 930830



#304 930830



#305 930830



#306 930830



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#307 930830



#308 930830



#309 930830



#310 930830



#311 930830



#312 930830



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#313 930830



#314 930040



#315 930040



#316 930040



#317 930040



#318 930040



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#319 930040



#320 930040



#321 930040



#322 930040




#323 930040



#324 835257



 <p>api CUSTOMIZED QUALITY ASSURANCE WORMS SAFETY</p>	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#325 835257



#326 835257



#327 835257



#328 835257



#329 835257



#330 835257



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#331 835257



#332 835257



#333 835257



#334 835257




#335 835257



#336 930847



 <p>api CUSTOMIZED QUALITY ASSURANCE WORMS SAFETY</p>	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#337 930847



#338 930847



#339 930847



#340 930847



#341 930847



#342 930847



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#343 930847



#344 930847



#345 930847



#346 930847




#347 930847



#348 930823



 api CUSTOMIZED QUALITY ASSURANCE WORMS SAFETY	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#349 930823



#350 930823



#351 930823



#352 930823



#353 930823



#354 930823



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#355 930823



#356 930823



#357 930823



#358 930823



#359 930844



#360 930844



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#361 930844



#362 930844



#363 930844



#364 930844



#365 930844



#366 930844



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#367 930844



#368 930844



#369 930844



#370 930844



#371 930039



#372 930039



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#373 930039



#374 930039



#375 930039



#376 930039



#377 930039



#378 930039



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#379 930039




#380 930039



#381 930039



#382 930828




#383 930828



#384 930828



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#385 930828



#386 930828



#387 930828



#388 930828



#389 930828



#390 930828



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#391 930828



#392 930828



#393 930828



#394 930849




#395 930849



#396 930849



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#403 930849



#404 930849



#405 930849



#406 932092




#407 932092



#408 932092



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#415 932092



#416 932092



#417 932092



#418 932080




#419 932080



#420 932080




	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#421 932080



#422 932080



#423 932080



#424 932080




#425 932080



#426 932080



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#427 932080



#428 932080



#429 932080



#430 932087




#431 932087



#432 932087




	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#433 932087



#434 932087



#435 932087



#436 932087




#437 932087



#438 932087



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#439 932087



#440 932087



#441 932087



#442 932082



#443 932082



#444 932082




INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#445 932082



#446 932082



#447 932082



#448 932082




#449 932082



#450 932082



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#451 932082



#452 932082



#453 932082



#454 932074




#455 932074



#456 932074



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#457 932074



#458 932074



#459 932074



#460 932074



#461 932074



#462 932074



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#463 932074



#464 932074



#465 932074



#466 932070




#467 932070



#468 932070




	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#469 932070



#470 932070



#471 932070



#472 932070




#473



#474 932070



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#475 932070



#476 932070



#477 932070



#478 932071




#479 932071



#480 932071



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#481 932071



#482 932071



#483 932071



#484 932071




#485 932071



#486 932071



	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#487 932071



#488 932071



#489 932071



#490 932079



#491 932079



#492 932079



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#499 932079



#500 932079



#501 932079



#502 932089



#503 932089



#504 932089



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#505 932089



#506 932089



#507 932089



#508 932089



#509 932089



#510 932089



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#511 932089



#512 932089



#513 932089



#514 930825




#515 930825



#516 930825




	INSPECTION REPORT	
	Inspection No	33505
	Product ref	833695
	Report No	33505-1

#517 930825



#518 930825



#519 930825



#520 930825



#521 930825



#522 930825



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#523 930825



#524 930825



#525 GS



#526 api stamp



#527 warehouse



#528 api stamp



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#529 warehouse



#530 GS




#531 all selected cartons




#532 all selected cartons



#533



#534



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#535



#536



#537



#538



#539



#540



INSPECTION REPORT

Inspection No	33505
Product ref	833695
Report No	33505-1

#541



#542



#543



#544




#545



#546



	INSPECTION REPORT		
	Inspection No	33505	
	Product ref	833695	
	Report No	33505-1	



For and on Behalf of
Asia Pacific Inspection (API)

**** END OF REPORT ****