


|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

## GENERAL INFORMATION

|                     |   |
|---------------------|---|
| Client name         | ADEO SERVICES                               |
| Service name        | Final Random Inspection                     |
| Supplier name       | MERIDIAN INTERNATIONAL CO, LTD              |
| Factory name        | MERIDIAN INTL.                              |
| Factory address     | #1886 Laiyin Rd, Songjiang, Shanghai, China |
| PO number           | S2009345314                                 |
| Product ref         | 895535                                      |
| Product desc.       | DEXTER 1 - 5PCS SCREWDRIVER SET             |
| Destination country | RUSSIA, ITALY                               |
| Insp. Date          | 29/06/2021 to 01/07/2021                    |
| Inspection office   | API SUZHOU                                  |
| Inspector Name      | Brady WU                                    |
| Production status   | 100%  |
| Packing status      | 100%  |



## INSPECTION SUMMARY


| Criteria              |                        | Results     | Remarks |
|-----------------------|------------------------|-------------|---------|
| A                     | Quantity               | PASS        |         |
| B                     | Workmanship            | PASS        |         |
| C                     | Product specifications | PASS        |         |
| D                     | Packing                | PASS        |         |
| E                     | Onsite tests           | PASS        |         |
| F                     | Other information      | PASS        |         |
| <b>OVERALL RESULT</b> |                        | <b>PASS</b> |         |

## WORKMANSHIP SUMMARY

| Inspection Standard | ANSI/ASQ Z1.4  | AQL           | Critical - 0 | Major - 1.5 | Minor - 4 |
|---------------------|----------------|---------------|--------------|-------------|-----------|
| Inspection Level    | Level I        |               |              |             |           |
| Sampling plan       | Normal, Single | Sampling size | 50           | 50          | 50        |
| Sampling size       | 50             | Max           | 0            | 2           | 5         |
| Lot size            | 1296           | Found         | 0            | 0           | 0         |
|                     |                | Result        | PASS         | PASS        | PASS      |

## ORDER DETAILS

| #            | Product ref | Item description                | EAN #         | PO          | Insp. Qty | Sample size |
|--------------|-------------|---------------------------------|---------------|-------------|-----------|-------------|
| 1            | 895535      | DEXTER 1 - 5PCS SCREWDRIVER SET | 3276000247296 | S2009345314 | 1296      | 50          |
| <b>Total</b> |             |                                 |               |             | 1296      | 50          |


|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

## PROBLEMATIC REMARKS

| # | Product ref | Remarks | Category | Result |
|---|-------------|---------|----------|--------|
| 1 | All         | Nil     |          |        |

## COMMENTS FOR INFORMATION

| # | Product ref | Comments   |
|---|-------------|--|
| 1 | 895535      | Factory no conditions to do thardness test and torque test                           |
| 2 | 895535      | Logistic data is over +/-5% tolerance, please refer to details in Logistic Data list |

|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

## A - QUANTITY

|                       |             |
|-----------------------|-------------|
| <b>Overall Result</b> | <b>PASS</b> |
|-----------------------|-------------|


## AVAILABLE QUANTITIES

| #            | Product ref | PO No.      | Booking QTY |         | Available QTY     |                     |              | Total         |               |
|--------------|-------------|-------------|-------------|---------|-------------------|---------------------|--------------|---------------|---------------|
|              |             |             |             |         | Finished & Packed | Finished & unpacked | Not Finished | % Finished    | % Packed      |
|              |             |             | Units       | Cartons | Units             | Units               | Units        |               |               |
| 1            | 895535      | S2009345314 | 1296        | 27      | <b>1296</b>       | <b>0</b>            | <b>0</b>     | <b>100.00</b> | <b>100.00</b> |
| <b>Total</b> |             |             | 1296        | 27      | 1296              | 0                   | 0            | <b>100%</b>   | <b>100%</b>   |

## SELECTED CARTONS QUANTITY

| #            | Product ref | PO No.      | Batch No.   | Select CTN QTY | CTN No.        |
|--------------|-------------|-------------|-------------|----------------|----------------|
| 1            | 895535      | S2009345314 | S2009345314 | 6              | 25 14 17 8 5 2 |
| <b>Total</b> |             |             |             | 6              |                |

## PHOTOS

|   |                          |         |             |
|---|--------------------------|---------|-------------|
|  <b>api</b><br>CUSTOMIZED<br>QUALITY<br>ASSURANCE<br>WORMS SAFETY | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|   | Inspection No            | 32188   |             |
|   | Product ref              | 895535  |             |
|   | Report No                | 32188-7 |             |


## B - WORKMANSHIP

|                       |             |
|-----------------------|-------------|
| <b>Overall Result</b> | <b>PASS</b> |
|-----------------------|-------------|

## DEFECTS RESULT

| # | Product ref | Defect description | Sample size        | Defect classification |              |             |
|---|-------------|--------------------|--------------------|-----------------------|--------------|-------------|
|   |             |                    |                    | Critical<br>0         | Major<br>1.5 | Minor<br>4  |
|   |             |                    | <b>Sample size</b> | 50                    | 50           | 50          |
|   |             |                    | <b>Max</b>         | 0                     | 2            | 5           |
|   |             |                    | <b>Found</b>       | 0                     | 0            | 0           |
|   |             |                    | <b>Result</b>      | <b>PASS</b>           | <b>PASS</b>  | <b>PASS</b> |

## PHOTOS

|  |                          |         |  |             |
|--|--------------------------|---------|--|-------------|
|  | <b>INSPECTION REPORT</b> |         |  | <b>PASS</b> |
|  | Inspection No            | 32188   |  |             |
|  | Product ref              | 895535  |  |             |
|  | Report No                | 32188-7 |  |             |

## C - PRODUCT SPECIFICATIONS

|                       |             |
|-----------------------|-------------|
| <b>Overall Result</b> | <b>PASS</b> |
|-----------------------|-------------|

### PRODUCT DIMENSION W/O PACKAGING

|                   |                      |              |   |       |    |                 |   |                     |            |
|-------------------|----------------------|--------------|---|-------|----|-----------------|---|---------------------|------------|
| * Tolerance used: | Client specification | Sample size: | 1 | Unit: | mm | Tolerance Type: | % | Tolerance apply on: | Individual |
|-------------------|----------------------|--------------|---|-------|----|-----------------|---|---------------------|------------|


| # | Product ref | Spec from client Values |   |   | Dimension pack info Values |   |   | Tol. * | # Pcs | Measured values |   |   | Discrepancy to Spec       | Discrepancy to Pack info   |
|---|-------------|-------------------------|---|---|----------------------------|---|---|--------|-------|-----------------|---|---|---------------------------|----------------------------|
|   |             | L                       | W | H | L                          | W | H |        |       | L               | W | H |                           |                            |
| 1 | 895535      | 210                     |   |   |                            |   |   | 3      | 1     | 210             |   |   | L +0%<br>W N/A%<br>H N/A% | L N/A%<br>W N/A%<br>H N/A% |

### PRODUCT WEIGHT W/O PACKAGING

|                   |                      |              |   |       |    |                 |   |
|-------------------|----------------------|--------------|---|-------|----|-----------------|---|
| * Tolerance used: | Client specification | Sample size: | 1 | Unit: | kg | Tolerance Type: | % |
|-------------------|----------------------|--------------|---|-------|----|-----------------|---|

| # | Product ref | Spec from client Values | Weight on pack Values | Tol. * | # Pcs | Measured values | Discrepancy to Spec | Discrepancy to Pack info |
|---|-------------|-------------------------|-----------------------|--------|-------|-----------------|---------------------|--------------------------|
| 1 | 895535      |                         |                       | 10     | 1     | 0.28            | N/A                 | N/A                      |

## PHOTOS

|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

## D - PACKING

### FINDINGS

| #                     | Product ref | Subcategory | Remark   | Result      |
|-----------------------|-------------|-------------|--|-------------|
| 1                     | All         | Dimension   | Logistic data is over +/-5% tolerance, please refer to details in Logistic Data list | COMMENT     |
| <b>Overall Result</b> |             |             |  | <b>PASS</b> |

### BARCODES (SAMPLE SIZE: DELIVERY PACKING 5 PCS, SALES PACKING S-3)

| # | Product ref | Packing type | Barcode | Visual check |      |      | Scancheck |      |      |
|---|-------------|--------------|---------|--------------|------|------|-----------|------|------|
|   |             |              |         | Sample       | Fail | Pass | Sample    | Fail | Pass |


### PACKING MATERIAL - OUTER CARTON

| # | Product ref | Export Carton | Corrugated paper plies | Fastening | Tape Sealing | Strapping  | Others |
|---|-------------|---------------|------------------------|-----------|--------------|------------|--------|
| 1 | 895535      | New           | Double                 | Glue      | Transparent  | Nylon band |        |

### MASTER CARTON WEIGHT CHECK

| Dev Limit (%)         |             |                           |       |       |       |       |         |                                      | 2           |                |
|-----------------------|-------------|---------------------------|-------|-------|-------|-------|---------|--------------------------------------|-------------|----------------|
| #                     | Product ref | Master Carton Weight (kg) |       |       |       |       |         | Weight printed on Master carton (kg) | Dev (%)     | Initial Result |
|                       |             | #1                        | #2    | #3    | #4    | #5    | Average |                                      |             |                |
| 1                     | 895535      | 17.96                     | 18.05 | 17.87 | 17.92 | 17.96 | 17.95   | 18                                   | -0.27       | PASS           |
| <b>Overall Result</b> |             |                           |       |       |       |       |         |                                      | <b>PASS</b> |                |


### PHOTOS

|   |                          |         |             |
|---|--------------------------|---------|-------------|
|  <b>api</b><br>CUSTOMIZED<br>QUALITY<br>ASSURANCE<br>WORMS SAFETY | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|   | Inspection No            | 32188   |             |
|   | Product ref              | 895535  |             |
|   | Report No                | 32188-7 |             |

## E - ONSITE TESTS

| #                     | Description              | Level  | Sample size | Fail | Pass | Comments | Result      |
|-----------------------|--------------------------|--------|-------------|------|------|----------|-------------|
| 1                     | Function Check           | S3     | 13          | 0    | 13   |          | PASS        |
| 2                     | Marking check            | S3     | 13          | 0    | 13   |          | PASS        |
| 3                     | Packaging Check          | I      | 50          | 0    | 50   |          | PASS        |
| 4                     | Part List Check          | I      | 50          | 0    | 50   |          | PASS        |
| 5                     | odor check               | Custom | 13          | 0    | 13   |          | PASS        |
| 6                     | Country speciality check | Custom | 1           | 0    | 1    |          | PASS        |
| <b>Overall Result</b> |                          |        |             |      |      |          | <b>PASS</b> |

## PHOTOS

|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

## F - OTHER INFORMATION

|                       |             |
|-----------------------|-------------|
| <b>Overall Result</b> | <b>PASS</b> |
|-----------------------|-------------|

## DOCUMENTS AVAILABLE DURING INSPECTION

| # | Inspection is performed with  |
|---|---|
| 1 | This inspection performed with PO and TCF.  |
| 2 | Inspection with "Control Plan packing and packaging control plan_generic_20150505" and Control Plan hand tools_20120112 |

## TYPE OF SAMPLE AVAILABLE DURING INSPECTION

| # | Product ref | Type of Sample | Description | Quantity | Comments |
|---|-------------|----------------|-------------|----------|----------|
| 1 | 895535      | Golden sample  | product     | 1        |          |

## PHOTOS

## PICTURES


### Product Ref: 895535

#1 Export Carton



#2 Export Carton-shipping mark



|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

#3 barcode



#4 Export Carton-open



#5 Inner box



#6 Inner box-mark




#7 Packaging



#8 Color card



|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

#9 Color card



#10 Color card



#11 Color card




#12 Color card




#13 Color card



#14 Color card



|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

#15 Color card



#16 Packaging



#17 product



#18 product



#19 product



#20 product



**INSPECTION REPORT**

|               |         |
|---------------|---------|
| Inspection No | 32188   |
| Product ref   | 895535  |
| Report No     | 32188-7 |

**PASS**

#21 product



#22 product



#23 product



#24 Dimension Check




#25 Dimension Check



#26 Weight Check



|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |

#27 Weight Check




#28 Approval sample



#29 Approval sample



#30 barcode scan




#31 Warehouse



#32 Open cartons



|  |                          |         |             |
|--|--------------------------|---------|-------------|
|  | <b>INSPECTION REPORT</b> |         | <b>PASS</b> |
|  | Inspection No            | 32188   |             |
|  | Product ref              | 895535  |             |
|  | Report No                | 32188-7 |             |



For and on Behalf of  
Asia Pacific Inspection (API)

**\*\* END OF REPORT \*\***